

RK3288/RK3368 TV Boxes Guides & Issue Tracker - Bug #15

Some airmouses like Mele F10 keep repeating keys on RK3288 firmware.

03/28/2016 07:52 AM - Redmine Admin

Status:	Resolved	Start date:	03/26/2016
Priority:	Urgent	Due date:	
Assignee:	Redmine Admin	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:			

Description

Some airmouses like Mele F10 keep repeating keys on RK3288 firmware.

It is most likely a USB driver bug.

In ChromeOS 3.14 kernel Rockchip released 2 patches that improves USB devices and stops keys repeating.

Maybe if it can be ported and adjusted for 3.10 Lollipop kernels it can help.

Here are the patches

<https://chromium-review.googlesource.com/#/c/323303/>

<https://chromium-review.googlesource.com/#/c/325027/>

History

#1 - 07/27/2016 09:08 PM - Redmine Admin

- Status changed from New to Resolved

- % Done changed from 0 to 100

Bug has been solved.

Airmouses function properly now.